

**325 King Street, Niagara-On-The-Lake, Ontario Arborist Report:  
Tree Inventory and Preservation  
Plan**

March 3, 2023

Prepared for:

Two Sisters Properties  
122 Romina Drive  
Concord, ON L4K 4Z7

Prepared by:

Stantec Consulting Ltd.

in Association With:

Buchanan Expert Tree Care Inc.



160940942

**325 KING STREET, NIAGARA-ON-THE-LAKE, ONTARIO ARBORIST REPORT: TREE INVENTORY AND PRESERVATION PLAN**

This document entitled 325 King Street, Niagara-On-The-Lake, Ontario Arborist Report and Tree Inventory Report was prepared by Stantec Consulting Ltd. in association with Buchanan Expert Tree Care Inc. (BETC). The report was prepared for Two Sisters Properties. in support of the development applications for lands located on the aforementioned property, 325 King Street in Niagara-On-The-Lake, Ontario (the "Project"). In connection thereto, this document may be reviewed and used by the provincial and municipal government agencies participating in the permitting process in the normal course of their duties. Except as set forth in the previous sentence, any reliance on this document by any third party for any other purpose is strictly prohibited. The material in this document reflects BETC's and Stantec's professional judgment in light of the scope, schedule and other limitations stated in the document and in the contract between BETC, Stantec and the Client. The opinions in the document are based on conditions and information existing at the time the document was published and do not take into account any subsequent changes. In preparing the document, Stantec and BETC did not verify information supplied to it by others. Any unauthorized use which a third party makes of this document is the responsibility of such third party. Such third party agrees that Stantec and BETC shall not be responsible for costs or damages of any kind, if any, suffered by it or any other third party as a result of decisions made or actions taken based on unauthorized use of this document.

Prepared by   
(signature)

**Bill Buchanan, HBSc Forestry**  
**ISA Board Certified Master Arborist NY-0392B**

Reviewed by   
(signature)

**David Waverman, CAHP, OALA, CSLA**  
**Senior Landscape Architect**

## Table of Contents

<b>1.0</b>	<b>INTRODUCTION</b> .....	<b>1.1</b>
<b>2.0</b>	<b>METHODOLOGY</b> .....	<b>2.1</b>
2.1.1	Tree Inventory Methodology .....	2.1
2.1.2	Town of Niagara-on-the-lake Tree Inventory Requirements .....	2.1
<b>3.0</b>	<b>DESCRIPTION OF THE STUDY AREA</b> .....	<b>3.1</b>
3.1	325 KING STREET .....	3.1
<b>4.0</b>	<b>SUMMARY OF FINDINGS</b> .....	<b>4.1</b>
4.1	ASSESSMENT OF TREE 28 – RED OAK .....	4.1
<b>5.0</b>	<b>TREE PRESERVATION, PROTECTION &amp; MANAGEMENT</b> .....	<b>5.1</b>
5.1	TREE PROTECTION BARRIERS: FENCING AND HOARDING .....	5.1
5.2	TREE MAINTENANCE .....	5.1
5.3	PRE-CONSTRUCTION MAINTENANCE .....	5.2
5.4	TREE MAINTENANCE DURING CONSTRUCTION .....	5.2
5.5	POST-CONSTRUCTION MAINTENANCE .....	5.3
5.6	TREE 28 .....	5.3
<b>6.0</b>	<b>DISCLAIMER</b> .....	<b>6.1</b>

### LIST OF TABLES

Table 1: Summary of Inventory .....	4.1
Table 2: Summary of Preservation .....	4.1

### LIST OF APPENDICES

- Appendix A: Town of Niagara-On-The-Lake List of Tree Inventory Requirements
- Appendix B: Tree Inventory Charts
- Appendix C: Photographic Inventory
- Appendix D: Tree Inventory Plans

# 325 KING STREET, NIAGARA-ON-THE-LAKE, ONTARIO ARBORIST REPORT: TREE INVENTORY AND PRESERVATION PLAN

Introduction  
March 3, 2023

## 1.0 INTRODUCTION

Stantec and Buchanan Expert Tree Care (BETC), were retained by Two Sisters Properties (the Property Owner) to prepare an Arborist Report including a Tree Inventory and Preservation Plan for the property located at 325 King Street (the Study Area), in the Town of Niagara-on-the-Lake, Ontario.

All tree inventory and assessments were conducted by Bill Buchanan, HBS Sc Forestry, ISA Board Certified Master Arborist NY-0392B. Graphic preparation was provided by Stantec. The tree inventory led by Bill Buchanan, ISA Board Certified Master Arborist was conducted on January 3, 2023.



# 325 KING STREET, NIAGARA-ON-THE-LAKE, ONTARIO ARBORIST REPORT: TREE INVENTORY AND PRESERVATION PLAN

Methodology  
March 3, 2023

## 2.0 METHODOLOGY

### 2.1.1 Tree Inventory Methodology

At the request of the Town, the following information on the inventoried trees was collected and appears graphically on the tree inventory plans; as text in the tree inventory charts, and as photographs, found in Appendices B, C and D respectively.

- 1) **Tree species**, scientific and common name.
- 2) **Diameter at Breast Height (DBH)** (metric). Measurement of the trunk at 1.4m above grade. Expressed as diameter in centimetres.
- 3) **Health Rating System**: The following health rating system has been used based on visual inspection of above ground parts of the trees.:
  - 0 – Dead, hazardous, or uprooting. Tree exhibits no signs of life. Needs removal.
  - 1 – Declining or diseased tree. Too weak to survive construction. Recommend removal.
  - 2 – Relatively healthy but less vigorous. Will struggle with construction.
  - 3 – Healthy and vigorous. Defects if present are minor (e.g., twig dieback, small wounds) Good chance of survival with construction depending on proximity.
- 4) **Photographic Record**: A photographic record of each individual tree was recorded and can be found in Appendix C.

### 2.1.2 Town of Niagara-on-the-lake Tree Inventory Requirements

The methodology used for the tree inventory was adopted from the tree inventory requirements provided by the Town of Niagara-on-the-lake. Refer to Appendix A for the full list of requirements.



# 325 KING STREET, NIAGARA-ON-THE-LAKE, ONTARIO ARBORIST REPORT: TREE INVENTORY AND PRESERVATION PLAN

Description of the Study Area.  
March 3, 2023

## 3.0 DESCRIPTION OF THE STUDY AREA.

### 3.1 325 KING STREET

The property at 325 King Street is a square shaped parcel bordered by Regent Street to the west, Centre Street to the south, King Street to the east, and Gage Street to the north, The property consists of mature coniferous and deciduous tree species of various health conditions, one irregularly shaped school building, a large grassed area, paved play area, semi-circle seating area, parking lot, underground railroad marker, and historical oak tree marker.



# 325 KING STREET, NIAGARA-ON-THE-LAKE, ONTARIO ARBORIST REPORT: TREE INVENTORY AND PRESERVATION PLAN

Summary of Findings  
March 3, 2023

## 4.0 SUMMARY OF FINDINGS

This section summarizes the findings of the tree inventory conducted on January 3, 2023, by Bill Buchanan, HBSc Forestry, ISA Board Certified Master Arborist with specific attention to tree 28. The detailed tree inventory chart is located in Appendix B, with information pertaining to tree species, DBH, health rating, ownership, tree removals, and additional comments.

**Table 1: Summary of Inventory**

Item	Description	Quantity
1	Total Number of Individual Trees Inventoried	46
2	Total Number of Trees Inventoried on Adjacent Properties	8
3	Total Number of Dead Trees on Subject Properties	1
4	Total Number of Dead Trees on Adjacent Properties	0

**Table 2: Summary of Preservation**

Item	Description	Quantity
1	Total Number of Individual Trees to be Preserved	26
2	Total Number of Individual Trees to be Transplanted	1
3	Total Number of Individual Trees to be Removed	19

### 4.1 ASSESSMENT OF TREE 28 – RED OAK

Based on observations on January 3, 2023, by Bill Buchanan, HBSc Forestry, ISA Board Certified Master Arborist assessment of tree 28, the tree is in a state of decline due to age and environmental factors. The explanation is as follows:

1. Red Oak (*Quercus rubra*) has a biological life expectancy of about 350 years. It is the opinion of the Master Arborist that the red oak tree is over 300 years old. A more accurate age can be determined, if required, by using an increment bore to count annual growth rings. Due to its age, the tree is in a state of decline called 'senescence'. It is similar to a person at the age of 100 and biological functions start failing which lead to natural death.
2. Signs of this decline are evident in the lack of twig elongation throughout the canopy. Also, the top outermost region of the canopy is developing dead limbs. This is typical of senescence because that is the farthest part of the tree that water needs to travel. With biological functions failing, that part of the tree suffers.
3. There are significant dead limbs throughout the canopy which is expected for a tree this age and a major crossing limb (50cm diameter) near the main crotch of the tree causing major decay.



# 325 KING STREET, NIAGARA-ON-THE-LAKE, ONTARIO ARBORIST REPORT: TREE INVENTORY AND PRESERVATION PLAN

Summary of Findings  
March 3, 2023

These items are more of an indication of the lack of care and maintenance that has occurred by the previous owner responsible for the health of the tree.

4. Lastly, there are signs of Phytophthora canker on the main trunk of the tree. This is also not uncommon but is another reason that this tree will have difficulty staying alive and healthy for any significant amount of time.

In summary, it is in the opinion of the master arborist that this tree will be short lived with or without Buchanan Expert Tree Care's involvement, but will be slightly longer with some care. Any and all construction, grade changes, and especially slight changes in the natural water table will greatly affect the tree's longevity.





# 325 KING STREET, NIAGARA-ON-THE-LAKE, ONTARIO ARBORIST REPORT: TREE INVENTORY AND PRESERVATION PLAN

Tree Preservation, Protection & Management  
March 3, 2023

## 5.0 TREE PRESERVATION, PROTECTION & MANAGEMENT

This section outlines the prescriptions for tree preservation, protection and maintenance pre-construction, during construction, and post construction. This includes the required tree removals, pruning, fertilizing, root pruning and protection, mulching, and installation of tree protection hoarding. All tree maintenance shall be carried out to the most current arboricultural standards and only by qualified arborists who are certified to practice in the province of Ontario. Work completed on site will adhere to the following by-laws:

1. Town By-law 4571-12, *A By-law to Authorize and Regulate the Planting, Care, Maintenance and Removal of Trees on the Town of Niagara-on-the-Lake's Property* (the "**Public Tree By-law**").
2. Town By-law 5139-19, *A By-law to Regulate the Destruction or Injuring of Trees on Private Property in the Urban Areas of the Municipality and to Rescind By-law 5106-18* (the "**Private Tree Bylaw**").

Trees recorded in the inventory are assigned one of two levels of protection and/or preservation/removal:

### 1. **Preserve, Protect & Maintain**

Includes protection with tree preservation hoarding, as well as pre- and post-construction arboricultural works

### 2. **Remove**

Due to site or development constraints, tree condition or location, retention is not possible or desirable

## 5.1 TREE PROTECTION BARRIERS: FENCING AND HOARDING

All trees scheduled to be Preserved, Protected & Maintained or Preserved & Protected shall have their critical rooting zones protected with the installation of tree protection barriers to form a Tree Protection Zone (TPZ).

Tree protection barriers shall be installed as per International Society of Arboriculture standards.

The tree protection barriers shall be installed at the approved location and shall be maintained in their original location and condition until all construction activities within the site have ceased and all equipment is removed from the site. No equipment or material storage, flushing of fuel or washing of equipment is allowed within the TPZ

## 5.2 TREE MAINTENANCE

Specifications for tree maintenance are outlined in this section. This includes maintenance prior to construction, remedial action during construction and post-construction maintenance.



Tree Preservation, Protection & Management  
March 3, 2023

### **5.3 PRE-CONSTRUCTION MAINTENANCE**

Prior to any construction works commencing, all trees scheduled to be Preserved, Protected & Maintained shall undergo preventative maintenance. This may include:

#### **i. Pruning**

Trees shall be properly pruned to encourage healthy, vigorous growth. This includes the removal of deadwood, and crown cleaning and thinning. Additionally, any branches or limbs found to interfere with the proposed construction works shall be removed at this time to prevent improper pruning or mechanical injury.

#### **ii. Root Bio-stimulants**

The critical rooting zones specified to be protected with tree protection hoarding shall be deep root bio-stimulated to assist the tree in mitigating any possible impacts or stresses caused by the proposed construction. A suspension formulation of sea kelp hormonal bio-stimulant with a complete micronutrient package shall be used. Delivery of the bio-stimulant formulation shall be by high pressure injection using water as a medium.

### **5.4 TREE MAINTENANCE DURING CONSTRUCTION**

During the construction phase of development, mitigation of problems caused by excavation and other construction activities must be addressed. This shall include:

#### **i. Excavation Monitoring & Root Pruning**

During construction, any excavation that will affect the critical rooting zones of a tree shall be monitored by a certified arborist. If, during the excavation, roots are injured or cut, the arborist shall prune or cut the injured root with a sharp implement. This will encourage callous formation and adventitious root sprouting.

#### **ii. Irrigation During construction**

Any trees that are subject to drought conditions shall have their critical root zones watered to maintain a moist/fresh moisture regime.

#### **iii. Accidental Damage to Trees**

If, during any phase of construction, damage occurs to any trees that are scheduled to be preserved, it is the responsibility of the contractor to immediately notify the Consulting Arborist. The consulting arborist shall prescribe the remedial works which shall commence immediately and at the owner's expense.



# 325 KING STREET, NIAGARA-ON-THE-LAKE, ONTARIO ARBORIST REPORT: TREE INVENTORY AND PRESERVATION PLAN

Tree Preservation, Protection & Management  
March 3, 2023

## 5.5 POST-CONSTRUCTION MAINTENANCE

Once construction activities are completed, any required remedial works shall be prescribed by the consulting arborist. This will include:

### i. Post-Construction Inspection

Evaluation of the current condition of preserved trees should be conducted. This will include examination of the critical root zone, examination of the tree for any mechanical injury and overall health.

### ii. Removal of Tree Protection Barriers

Upon the approval of the Town of Niagara of the Lake, all tree protection barriers can be removed

## 5.6 TREE 28

As a result of the assessment denoted in Section 4.1 of this report, extra caution will be taken during preservation, protection, and maintenance measures for tree 28. For example, the tree protection zone will be located at the dripline or as near as possible with respect to required construction.



# 325 KING STREET, NIAGARA-ON-THE-LAKE, ONTARIO ARBORIST REPORT: TREE INVENTORY AND PRESERVATION PLAN

Disclaimer  
March 3, 2023

## 6.0 DISCLAIMER

The assessment of the trees presented within this report has been made using accepted arboricultural techniques. These include a visual examination of the above-ground parts of each tree for structural defects, scars, external indications of decay, evidence of insect presence, discoloured foliage, the general condition of the trees and the surrounding site, as well as the proximity of property and people.

Notwithstanding the recommendations and conclusions made in this report, it must be realized that trees are living organisms and their health and vigour is constantly changing. They are not immune to changes in site conditions or seasonal variations in the weather.

**This report was completed prior to the finalization of the Grading Plan. Final preservation and removal recommendations for trees will be determined upon completion of final Grading and Composite Utility Plans.**

While reasonable efforts have been made to ensure the trees recommended for retention are healthy, no guarantees are offered or implied, that these trees or any part of them will remain standing. It is both professionally and practically impossible to predict with absolute certainty the behavior of any single tree or group of trees in all circumstances. Inevitably a standing tree will always pose some risk. Most trees have the potential for failure if provided with the necessary combinations of stresses and elements. This risk can only be eliminated if the tree is removed.

Although every effort has been made to ensure that this assessment is reasonably accurate, the trees should be re-assessed periodically. The assessment presented in this report is valid at the time of inspection.



# **APPENDIX A: Town of Niagara-On-The-Lake List of Tree Inventory Requirements**

## **Original List of Tree Inventory Requirements from the Town of Niagara-on-the-Lake**

---

### ***TERMS OF REFERENCE***

*Given this history and context, we are looking for an Arborist Report and Tree Inventory that includes:*

- 1. Trees on adjacent private and municipal lands that are within 6 m of the Subdivision Property boundary.*
- 2. Identification and use of the minimum DBH for trees to be surveyed as per ISA standards. Survey all trees that meet that standard. Include DBH in Tree Inventory Chart.*
- 3. DBH in metric.*
- 4. An indication as to whether tree canopies shown are conceptual or accurate.*
- 5. A Health Rating System based on the tree health in its current condition.*
- 6. A Tree Inventory that identifies and differentiates trees proposed for removal due to poor health v. the proposed development.*
- 7. Photos sufficient to assess tree character and the basis for the health rating assigned.*
- 8. The dates for site visits or visual inspections.*

# APPENDIX B: Tree Inventory Charts





Tree#	Common Name	Botanical Name	DBH	Health Rating	Tree to be Removed	Ownership	Comments	Additional Removal Comments
1	Money Spruce	<i>Abies</i>	66	3		Private	Healthy	
2	White Redgum	<i>Morus alba</i>	18	2		Private	White stem, whether recommended removal/pruning this tree	
3	White Redgum	<i>Morus alba</i>	22	2		Private	White stem, whether recommended removal/pruning this tree	
4	White Pine	<i>Pinus strobus</i>	56	2		Private	poor colour in thangs, low growth rate	
5	White Pine	<i>Pinus strobus</i>	34	2		Private	poor colour in thangs, low growth rate	
6	Silver Maple	<i>Acer saccharinum</i>	66	2		Private	poor canopy structure, low decline	
7	White Pine	<i>Pinus strobus</i>	40	2		Private	poor colour in thangs, low growth rate	
8	White Pine	<i>Pinus strobus</i>	58	2		Private	poor colour in thangs, low growth rate	
9	White Pine	<i>Pinus strobus</i>	50	2		Private	poor colour in thangs, low growth rate	
10	White Pine	<i>Pinus strobus</i>	52	2		Private	poor colour in thangs, low growth rate	
11	Silver Mahoe	<i>Morus alba</i>	68	3		Private	poor health	
12	White Mahoe	<i>Morus alba</i>	22	2		Private	additive - remove	
13	White Mahoe	<i>Morus alba</i>	10	2		Private	additive's irregularities with growth	
14	White Ash	<i>Fraxinus americana</i>	14	3		Private	additive (not preferred) remove	
15	Silver Maple	<i>Acer saccharinum</i>	104	1		Private	poor structure, canopy declining - remove	ownership to be determined, recommended removal due to health
16	Silver Maple	<i>Acer saccharinum</i>	102	1		Private	poor structure, canopy declining - remove	ownership to be determined, recommended removal due to health
17	Money Spruce	<i>Abies</i>	68	3		Private	poor health	
18	Money Spruce	<i>Abies</i>	41	1		Private	poor health, might have some deciduous removal	
19	Money Spruce	<i>Abies</i>	64	3		Private	good health	
20	Money Spruce	<i>Abies</i>	48	2		Private	good health	
21	Money Spruce	<i>Abies</i>	38	2		Private	poor health, some low lying growth	
22	Money Spruce	<i>Abies</i>	50	2		Private	poor health, some low lying growth	
23	Money Spruce	<i>Abies</i>	58	3		Private	good health	
24	Money Spruce	<i>Abies</i>	38	1		Private	good health	
25	Money Spruce	<i>Abies</i>	56	3		Private	good health	
26	Money Spruce	<i>Abies</i>	24	3		Private	good health	
27	Money Spruce	<i>Abies</i>	16	2		Private	poor low growth	
28	Red Oak	<i>Quercus alba</i>	112	1		Private	poor low growth	
29	Red Oak	<i>Quercus alba</i>	112	1		Private	poor low growth	
30	Silver Maple	<i>Acer saccharinum</i>	106	1		Private	poor canopy, declining, poor health	
31	Money Spruce	<i>Abies</i>	68	3		Private	poor health, low decline	
32	Money Spruce	<i>Abies</i>	68	1		Private	poor health, low decline	
33	Money Spruce	<i>Abies</i>	122	1		Private	poor health, low decline	
34	Money Spruce	<i>Abies</i>	60	2		Private	poor health, low decline	
35	White Pine	<i>Pinus strobus</i>	34	1		Private	poor health, low decline	
36	White Pine	<i>Pinus strobus</i>	66	0		Private	poor health, low decline	
37	White Pine	<i>Pinus strobus</i>	52	1		Private	poor health, low decline	
38	White Pine	<i>Pinus strobus</i>	72	2		Private	poor health, low decline	
39	White Pine	<i>Pinus strobus</i>	34	3		Private	poor health, low decline	
40	White Pine	<i>Pinus strobus</i>	40	2		Private	poor health, low decline	
41	White Pine	<i>Pinus strobus</i>	62	2		Private	poor health, low decline	
42	White Pine	<i>Pinus strobus</i>	68	2		Private	poor health, low decline	
43	White Pine	<i>Pinus strobus</i>	116	2		Private	poor health, low decline	
44	White Pine	<i>Pinus strobus</i>	116	2		Private	poor health, low decline	
45	White Pine	<i>Pinus strobus</i>	36	1		Private	poor health, low decline	
46	White Pine	<i>Pinus strobus</i>	32	3		Private	poor health, low decline	





**Health Rating:**  
0 - Stable, hardiness, or spreading. The analysis is right of the, health normal.  
1 - Declining or diseased tree. Too weak to survive construction, recommended removal.  
2 - Maturely healthy but not vigorous, will struggle with construction.  
3 - Healthy and vigorous, defects if present are minor (e.g. long cracks, small wounds) good chance of survival with construction depending on proximity.





**DBH:**  
The DBH data documented in this chart was retained from Cahill Consulting Inc's January 31st, 2020 report, "Tree Inventory and Assessment - Parliament Oak School Property, Town of Niagara on the Lake".







# APPENDIX C: Photographic Inventory





Tree #	Botanical Name	Common Name	Tree Photo
1	Norway Spruce	<i>Picea abies</i>	
2	White Mulberry	<i>Morus alba</i>	
3	White Mulberry	<i>Morus alba</i>	
4	White Pine	<i>Pinus strobus</i>	





5	White Pine	<i>Pinus strobus</i>	
6	Silver Maple	<i>Acer saccharinum</i>	
7 (Tree on Left)	White Pine	<i>Pinus strobus</i>	
8	White Pine	<i>Pinus strobus</i>	





<p>9 (Left Tree)</p>	<p>White Pine</p>	<p><i>Pinus strobus</i></p>	
<p>10 (Right Tree)</p>	<p>White Pine</p>	<p><i>Pinus strobus</i></p>	
<p>11</p>	<p>Sugar Maple</p>	<p><i>Acer saccharum</i></p>	
<p>12</p>	<p>White Mulberry</p>	<p><i>Morus alba</i></p>	

13	Red Oak	<i>Quercus rubra</i>	
14	White Ash	<i>Fraxinus americana</i>	
15	Silver Maple	<i>Acer saccharinum</i>	
16	Silver Maple	<i>Acer saccharinum</i>	











17	Norway Spruce	<i>Picea abies</i>	
18	Norway Spruce	<i>Picea abies</i>	
19	Norway Spruce	<i>Picea abies</i>	
20	Norway Maple	<i>Acer platanoides</i>	





21	Norway Maple	<i>Acer platanoides</i>	
22	Norway Maple	<i>Acer platanoides</i>	
23	Norway Maple	<i>Acer platanoides</i>	
24	Norway Maple	<i>Acer platanoides</i>	





25	Red Oak	<i>Quercus rubra</i>	
26	Red Oak	<i>Quercus rubra</i>	
27	Norway Maple	<i>Acer platanoides</i>	
28	Red Oak	<i>Quercus rubra</i>	





29	Silver Maple	<i>Acer saccharinum</i>	
30	Yew	<i>Taxus canadensis</i>	
31	Norway Maple	<i>Acer platanoides</i>	
32	Silver Maple	<i>Acer saccharinum</i>	

33	Sycamore	<i>Platanus occidentalis</i>	
34	Norway Maple	<i>Acer platanoides</i>	
35	White Ash	<i>Fraxinus americana</i>	
36	White Pine	<i>Pinus strobus</i>	


37	Silver Maple	<i>Acer saccharinum</i>	 A photograph of a Silver Maple tree (Acer saccharinum) in winter. The tree is tall and slender with a light-colored trunk and bare, spreading branches. It is situated outdoors near a building.
38	Blue Spruce	<i>Picea pungens</i>	 A photograph of a Blue Spruce tree (Picea pungens) in winter. The tree is a dense, conical evergreen with dark green needles. It is located in a park-like setting with a bench visible in the background.
39	Norway Maple	<i>Acer platanoides</i>	 A photograph of a Norway Maple tree (Acer platanoides) in winter. The tree has a thick trunk and a wide, spreading canopy of bare branches. The ground is covered in snow, and a building is visible in the background.
40	Basswood	<i>Tilia americana</i>	 A photograph of a Basswood tree (Tilia americana) in winter. The tree has a thick trunk and a dense canopy of bare branches. The ground is covered in snow, and a building is visible in the background.

41	Basswood	<i>Tilia americana</i>	
42	Silver Maple	<i>Acer saccharinum</i>	
43	Sugar Maple	<i>Acer saccharum</i>	
44	Silver Maple	<i>Acer saccharinum</i>	

45	Sycamore	<i>Platanus occidentalis</i>	
46	Silver Maple	<i>Acer saccharinum</i>	

# APPENDIX D: Tree Inventory Plans





**BUCHANAN**  
 Project tree map

Copyright Reserved  
 This Content and all other content is the property of Stantec. No part of this content may be reproduced or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or by any information storage and retrieval system, without prior written permission from Stantec. All rights reserved.



- Legend**
- Existing Deciduous Tree
  - Existing Coniferous Tree
  - (with 'X') Tree to be Removed
  - (with 'S') Schematic Tree Preservation (STP)
  - (with 'P') Schematic Tree Preservation (STP)
  - (with 'X') Tree to be Removed

Note: Tree canopy size and location have been inspected from aerial photography.

DATE	BY	DESCRIPTION

Permit/Seal

**PRELIMINARY  
 NOT FOR  
 CONSTRUCTION**

Not for permits, pricing or other official purposes. This document has not been completed or checked and is for general information only.

Project: SOLMAR (Niagara 2) Corp.  
 325 KING STREET  
 NIAGARA-FALLS, ONTARIO, CANADA

Title: EXISTING TREE INVENTORY AND PRESERVATION PLAN - FULL SITE

Project No. 14267912 Scale: 1:500  
 Revision: 01 of 3 Date: 08/11/2014  
 Drawing No. L-1



Stantec Consulting Ltd.  
100 King Street West  
Toronto, Ontario M5X 1C7  
Tel: (416) 591-1111  
www.stantec.com

**BUCHANAN**  
Registered Tree Care

Copyright Reserved  
This document is the property of Buchanan Registered Tree Care. No part of this document may be reproduced or transmitted in any form or by any means electronic or mechanical, including photocopying, recording, or by any information storage and retrieval system, without the prior written permission of Buchanan Registered Tree Care.

Key Map NTS



**Legend**

- Existing Deciduous Tree
- Existing Coniferous Tree
- Deceased Tree

Tree #	Common Name	Botanical Name	DBH	Health Rating	Trees to be Removed	Ownership	Comments	Additional Removal Comments
1	Norway Spruce	<i>Picea abies</i>	66	3		Private	healthy	
2	White Mulberry	<i>Morus alba</i>	18	2		Private	multi-stem volunteer; recommend removal/grow in site fence	
3	White Mulberry	<i>Morus alba</i>	22	2		Private	multi-stem volunteer; recommend removal/grow in site fence	
4	White Pine	<i>Pinus strobus</i>	56	2		Private	Poor colour in foliage/low growth rate	
5	White Pine	<i>Pinus strobus</i>	14	2		Private	Poor colour in foliage/low growth rate	
6	Silver Maple	<i>Acer saccharinum</i>	86	2		Private	poor canopy structure/some decline	
7	White Pine	<i>Pinus strobus</i>	40	2		Private	Poor colour in foliage/low growth rate	
8	White Pine	<i>Pinus strobus</i>	58	2		Private	Poor colour in foliage/low growth rate	
9	White Pine	<i>Pinus strobus</i>	50	2		Private	Poor colour in foliage/low growth rate	
10	White Pine	<i>Pinus strobus</i>	52	2		Private	Poor colour in foliage/low growth rate	
11	Sugar Maple	<i>Acer saccharum</i>	68	3		Private	good health	
12	White Mulberry	<i>Morus alba</i>	22	2	X	Private	volunteer - remove	
13	Red Oak	<i>Quercus rubra</i>	10	3		Private	small/tree/s transplantable with spade	
14	White Ash	<i>Fraxinus americana</i>	14	2	X	Private	volunteer (not planted) / remove	
15	Silver Maple	<i>Acer saccharinum</i>	104	1	X	Private	poor structure/major cavities/declining - remove	Ownership to be determined. Recommended removal due to health.
16	Silver Maple	<i>Acer saccharinum</i>	102	1	X	Private	poor structure/major cavities/declining - remove	Ownership to be determined. Recommended removal due to health.
17	Norway Spruce	<i>Picea abies</i>	68	3		Private	good health	
18	Norway Spruce	<i>Picea abies</i>	44	1	X	Private	good healthy/major base wound/damage remove	
19	Norway Spruce	<i>Picea abies</i>	64	3		Private	good health	
20	Norway Maple	<i>Acer platanoides</i>	46	2		Private	decent health/poor twig growth	
21	Norway Maple	<i>Acer platanoides</i>	58	2		Private	decent health/poor twig growth	
22	Norway Maple	<i>Acer platanoides</i>	90	2		Private	decent health/poor twig growth	
23	Red Oak	<i>Quercus rubra</i>	58	3		Private	good health	
24	Norway Maple	<i>Acer platanoides</i>	58	1	X	Private	poor structure/declining	Ownership to be determined. Recommended removal due to health.
25	Red Oak	<i>Quercus rubra</i>	56	3	X	Private	good health	
26	Red Oak	<i>Quercus rubra</i>	24	3	X	Private	good health	
27	Norway Maple	<i>Acer platanoides</i>	36	2		Private	poor twig growth	
28	Red Oak	<i>Quercus rubra</i>	132	1	X	Private	100yr old/major deadwood/principal/major leaders contain multi-stem/poor twig growth/long time to replace	
29	Silver Maple	<i>Acer saccharinum</i>	196	1	X	Public	major cavities/declining/poor health	
30	Few	<i>Taxus canadensis</i>	24	3		Private	healthy/cold	
31	Norway Maple	<i>Acer platanoides</i>	66	1	X	Private	poor health/multi-stem	Ownership to be determined. Recommended removal due to health.
32	Silver Maple	<i>Acer saccharinum</i>	123	1	X	Private	declining/cavities/multi-stem/remove	Ownership to be determined. Recommended removal due to health.
33	Sycamore	<i>Platanus occidentalis</i>	60	2		Private	major trunk crack/healthy	
34	Norway Maple	<i>Acer platanoides</i>	34	1	X	Private	poor health/landscaping tree with Sycamore/remove	
35	White Ash	<i>Fraxinus americana</i>	66	0	X	Private	dead/ remove	
36	White Pine	<i>Pinus strobus</i>	52	1	X	Private	poor colour / low growth rate	
37	Silver Maple	<i>Acer saccharinum</i>	72	3	X	Private	poor structure/multi-stem	
38	Rose Sycamore	<i>Picea pungens</i>	24	3	X	Private	good health	
39	Norway Maple	<i>Acer platanoides</i>	40	2	X	Private	poor structure/multi-stem	
40	Bananaeum	<i>Tilia americana</i>	82	2		Public	multi-stem/trunk wound/poor structure	
41	Bananaeum	<i>Tilia americana</i>	68	2		Public	multi-stem/trunk wound/poor structure	
42	Silver Maple	<i>Acer saccharinum</i>	116	2		Public	poor structure/cavities	
43	Sugar Maple	<i>Acer saccharum</i>	18	3		Public	young/healthy	
44	Silver Maple	<i>Acer saccharinum</i>	96	1	X	Public	multiple cavities/recently pruned/declining	Ownership to be determined. Recommended removal due to health.
45	Sycamore	<i>Platanus occidentalis</i>	22	3		Public	young/healthy/healthy	
46	Silver Maple	<i>Acer saccharinum</i>	108	1	X	Public	multi leaders/multiple cavities/declining	Ownership to be determined. Recommended removal due to health.

**Health Rating:**  
 0 = Dead, hazardous, overtopping. Trees exhibit no signs of life. Needs removal.  
 1 = Declining or diseased tree. Too weak to survive construction. Recommend removal.  
 2 = Relatively healthy but less vigorous. Will struggle with construction.  
 3 = Healthy and vigorous. Defects if present are minor (e.g. twig dieback, small wounds) Good chance of survival with construction depending on proximity.

**DBH:**  
 The DBH data documented in this chart was retained from Coville Consulting Inc's January 31st 2020 report, "Tree Inventory and Assessment - Parliament Oak School Property, Town of Niagara-on-the-Lake".

**TREE INVENTORY CONDUCTED ON JANUARY 3RD, 2023 BY:  
 BILL BUCHANAN, HBSFORESTRY, ISA BOARD CERTIFIED MASTER ARBORIST NY-0392B**

PROJECT: TREE INVENTORY AND PRESERVATION PLAN  
 Revision: 001  
 Date: 2023-01-03  
 Scale: 1:1000  
 Drawing No: 2 of 3

**PRELIMINARY NOT FOR CONSTRUCTION**

Not for permit, unless with the official approval. This document has not been completed or checked and is for reference purposes only.


Client/Project:  
 SOLMAR (Niagara 2) COID

325 KING STREET  
 NIAGARA-ON-THE-LAKE  
 ONTARIO, CANADA


Title:  
 EXISTING TREE INVENTORY AND PRESERVATION PLAN  
 TREE INVENTORY/REMOVAL TABLE

Project No.: 1016242  
 Scale: 1:1000  
 Revision: Sheet 2 of 3  
 Drawing No: L-2





- NOTES:
1. ATTACHMENT OF FENCE TO TREES WILL NOT BE PERMITTED.
  2. ANY SPACES BETWEEN FENCES SHALL BE PROTECTED WITH RIGID MATERIALS.
  3. UNLESS OTHERWISE SPECIFIED, ALL ANY CONSTRUCTION MATERIALS, EQUIPMENT OR VEHICLES BE PLACED WITHIN THE TREE PROTECTION FENCE.
  4. ALL TREE PROTECTION SHALL BE ERECTED PRIOR TO ANY CONSTRUCTION ACTIVITY AND IS TO REMAIN IN PLACE UNTIL ALL CONSTRUCTION HAS COMPLETED. CONSTRUCTION SHALL BE STOPPED IMMEDIATELY IN THE EVENT OF DAMAGE TO TREES OR FENCES.
  5. ALL TREE PROTECTION SHALL BE REMOVED PRIOR TO PROJECT FINAL ACCEPTANCE.
  6. REGULAR CONTROL FENCING WILL BE INSTALLED INDEPENDENTLY UNDER SUPERVISION OF THE ENVIRONMENTAL SUPERVISOR.



- NOTES:
1. ATTACHMENT OF FENCE TO TREES WILL NOT BE PERMITTED.
  2. ANY SPACES BETWEEN FENCES SHALL BE PROTECTED WITH RIGID MATERIALS.
  3. UNLESS OTHERWISE SPECIFIED, ALL ANY CONSTRUCTION MATERIALS, EQUIPMENT OR VEHICLES BE PLACED WITHIN THE TREE PROTECTION FENCE.
  4. ALL TREE PROTECTION SHALL BE ERECTED PRIOR TO ANY CONSTRUCTION ACTIVITY AND IS TO REMAIN IN PLACE UNTIL ALL CONSTRUCTION HAS COMPLETED. CONSTRUCTION SHALL BE STOPPED IMMEDIATELY IN THE EVENT OF DAMAGE TO TREES OR FENCES.
  5. ALL TREE PROTECTION SHALL BE REMOVED PRIOR TO PROJECT FINAL ACCEPTANCE.




Stantec Consulting Ltd.  
100 King Street West  
Toronto, Ontario M5X 1C4  
Tel: (416) 591-4110  
www.stantec.com



Copyright Reserved  
This document is the property of Buchanan Project Tree Care. It is not to be distributed, copied, or reproduced in any form without the written consent of Buchanan Project Tree Care. The Company and its employees shall not be held liable for any damages, including consequential damages, arising from the use of this document.

Key Map: NTC



- Legend
- Existing Curbside Tree
  - Existing Overhead Line
  - Existing Underground Line
  - Construction

DATE	DESCRIPTION	BY	APP'D
2023.08.04	ISSUE FOR PERMIT AND PRESERVATION PLAN	ES	CS/STP
2023.08.04	REVISION/ISSUE	ES	CS/STP

Permit Scale: 1:50

**PRELIMINARY NOT FOR CONSTRUCTION**

Not for permit, pricing or other official purposes. This document has not been completed or checked and is for informational purposes only.

Client/Project:  
SOLMAR (Niagara 2) Corp.  
325 KING STREET  
NAGARA-ON-THE-LAKE  
ONTARIO, CANADA

Title:  
EXISTING TREE INVENTORY  
AND PRESERVATION PLAN DETAILS

Project No.: 1524-012  
Scale:  
Revision: Sheet 3 of 3  
Drawing No.: L-901