


**Legend**

Property

'Nodes'

Estate Support and Maintenance

'Rooms'

Axial Walkway

Whistle Stop

Pool Complex

Orchard

Semi-circular Access Framing the Lily Pond

NOTE(S)

1. All locations are approximate.

REFERENCE(S)

1. "Orthophoto Mapping, Niagara Region 10cm 2018," 2018, Orthophotography Tile, First Base Solutions MapWarehouse, Tile orth176560478902018fbs, <https://maps.firstbasesolutions.com/map.php>.
 2. "Orthophoto Mapping, Niagara Region 10cm 2018," 2018, Orthophotography Tile, First Base Solutions MapWarehouse, Tile orth176560478952018fbs, <https://maps.firstbasesolutions.com/map.php>.
 3. "Orthophoto Mapping, Niagara Region 10cm 2018," 2018, Orthophotography Tile, First Base Solutions MapWarehouse, Tile orth176565478952018fbs, <https://maps.firstbasesolutions.com/map.php>.
 4. "Orthophoto Mapping, Niagara Region 10cm 2018," 2018, Orthophotography Tile, First Base Solutions MapWarehouse, Tile orth176565478902018fbs, <https://maps.firstbasesolutions.com/map.php>.
 Portions of this document include intellectual property of Esri and its licensors and are used under license. Copyright (C)2020 Esri and its licensors. All rights reserved.

TITLE

'Rooms' and 'Nodes' on the Property

CLIENT

Town of Niagara-on-the-Lake

PROJECT

Cultural Heritage Evaluation Report
 200 John Street East, Niagara-on-the-Lake

PROJECT NO. LHC0119

CONSULTANT

YYYY-MM-DD

2021-06-23

PREPARED

LHC

DESIGNED

JG

FIGURE #

18