

Site Images – July 23, 2024

12 Princess Street – St. Saviour's the Brock Memorial Church

- Images showing deteriorating condition of wood in the church steeple



Figure 1: View of Steeple on Façade



Figure 2: View of Steeple on the Northwest Corner



Figure 3: View of Round Window on Façade